


Hawaii - Aquifer Sector 07



Hydrogeologic Setting ⁽¹⁾Island of Hawaii - 0701 Northwest Mauna Loa Aquifer Sector, Anaehoomalu Aquifer SystemSpatial Description (optional) ⁽²⁾Map Available (optional) ⁽³⁾Map availableData Reporting Period ⁽⁴⁾April 1998 - April 2000

Source Type ⁽⁵⁾	Number of sites ⁽⁶⁾	Number of sites with confirmed ground water contamination ⁽⁶⁾	Number of sites that are listed and/or have confirmed releases ⁽⁶⁾	Contaminants ⁽⁷⁾	Number of site investigations (optional)	Number of sites that have been stabilized or have had the source removed (optional)	Number of sites with corrective action plans (optional)	Number of sites with active remediation (optional)	Number of sites with cleanup completed (optional)
NPL	0	0	0						
CERCLIS (non-NPL)	1	0	1	uncertain					
DOD/DOE	0	0	0						
LUST	2	0	2	petroleum			2		
RCRA Corrective Action	0	0	0						
Underground Injection	3	0	0						
State Sites	0	0	0						
Non-point source	0	0	0						
Other (specify)									

NPL - National Priority List

CERCLIS (non-NPL) - Comprehensive Environmental Response, Compensation, and Liability Information System

DOE - Department of Energy

DOD - Department of Defense

LUST - Leaking Underground Storage Tanks

RCRA - Resource Conservation and Recovery Act